## Title: Turbine starting to yaw in presence of a helicopter

## Section 1: What happened?

- When a helicopter was finished hoisting on an offshore wind farm and was moving away from the turbine, the pilot saw that the helicopter hoist lamp (indicating that the turbine is stopped) was not lit anymore, and the turbine was starting to yaw into the wind.
- No danger to any technicians at any time.

## Section 2: Why did it happen?

• The yaw request was not closed in proper time, leading to misunderstanding.

## Section 3: What did they learn?

• Helicopters need to have left the wind farm before any turbines can be restarted.